






ACCEPTABLE INCOMING LINE DIRECTIONS
POSITION TIE RODS TO AVOID INTERFERENCE WITH LINE
THREE TIE RODS MUST BE USED AT ALL TIMES



TENSION MOUNT OR
OVERWRAPPED LINE FEED
REQUIRES THE ADDITIONAL
USE OF ONE OR MORE SIDE
MOUNTING POSITIONS IN
ADDITION TO BASE MOUNT

