






ACCEPTABLE INCOMING LINE DIRECTIONS  
POSITION TIE RODS TO AVOID INTERFERENCE WITH LINE  
THREE TIE RODS MUST BE USED AT ALL TIMES



TENSION MOUNT OR  
OVERWRAPPED LINE FEED  
REQUIRES THE ADDITIONAL  
USE OF ONE OR MORE SIDE  
MOUNTING POSITIONS IN  
ADDITION TO BASE MOUNT

